



LEGEND

M1 = MOTORS 1,2,3,4,5,6
 GRD = GROUND
 FACTORY WIRING —————
 FIELD WIRING - - - - -

1. USE COPPER CONDUCTORS ONLY
 2. UNIT MUST BE GROUNDED
 3. FOR MOTOR AMPS SEE RATING STICKER ON OUTSIDE OF UNIT.



UNIT TERMINAL BOARD
 WIRING CONNECTION
 POINTS



MOTOR	SPEED 1 (RPM)	SPEED 2 (RPM)	SPEED 3 (RPM)	WHEN VIEW FROM BLADE END
3707-1	900	600	1200	CCW
3707-2	900	600	1800	CCW
3707-3	900	600	1800	CW
3707-4	1000	1400	1800	CCW
3707-5	600	1200	1800	CCW
3707-6	1550	1550	1550	CCW
3707-7	1800	600	1200	CCW
3707-8	600	1500	900	CCW

	MOTOR WIRING	FACTORY WIRING
CONTROL	BLACK	RED
PHASE (L1)	BROWN	BLACK
NEUTRAL	BLUE	WHITE

GENERAL SPECS		UNLESS OTHERWISE SPECIFIED DIMENSION ARE IN INCHES	
		TOLERANCES ARE:	
		FRACTIONS	DECIMALS ANGLES
		± 1/16	.X ± .12 .X ± .5°
			.XX ± .06
			.XXX ± .015
		FIN HEIGHT	FIN LENGTH
		± 1/16	± 1/8
CAD GENERATED DRAWING, DO NOT MANUALLY UPDATE DO NOT SCALE DRAWING			

LRC COIL CO.

WIRING DIAGRAM FOR Q UNIT - 1,2,3 FAN

SIZE A DWG. NO. Q WIRING DIAGRAM

SCALE DRAWN: DATE: 11/05/2017

REV.	DESCRIPTION	DATE	BY

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF LRC COIL CO. ANY REPRODUCTION IN PART OR WHOLE WITHOUT THE WRITTEN PERMISSION OF LRC COIL CO. IS PROHIBITED