




LEGEND

M1 = MOTORS 1,2,3,4,5,6

GRD = GROUND

FACTORY WIRING

FIELD WIRING

1. USE COPPER CONDUCTORS ONLY

2. UNIT MUST BE GROUNDED

3. FOR MOTOR AMPS SEE RATING STICKER ON OUTSIDE OF UNIT.

C-NC STD
SPEED 1 DEFAULT SPEED

CONTROL (NOT CONNECTED) RED
PHASE (L1) BLACK
NEUTRAL WHITE 110 V

C-N
SPEED 2 *

CONTROL RED
PHASE (L1) BLACK
NEUTRAL WHITE
(REVERSE AIRFLOW) 110 V

C-P
SPEED 3

CONTROL RED
PHASE (L1) BLACK
NEUTRAL WHITE 110 V

UNIT TERMINAL BOARD
WIRING CONNECTION
POINTS

GRD: GREEN
SCREW

	MOTOR WIRING	FACTORY WIRING
CONTROL	BLACK	RED
PHASE (L1)	BROWN	BLACK
NEUTRAL	BLUE	WHITE

***FLIP FAN BLADE WHEN
CONNECTING TO SPEED 2**

UNLESS OTHERWISE SPECIFIED DIMENSION ARE IN INCHES		
TOLERANCES ARE:		
FRACTIONS ± 1/16	DECIMALS .X ± .12 .XX ± .06 .XXX ± .015	ANGLES .X ± .5°
FIN HEIGHT ± 1/16	FIN LENGTH ± 1/8	
CAD GENERATED DRAWING, DO NOT MANUALLY UPDATE DO NOT SCALE DRAWING		

LRC COIL CO.

**WIRING DIAGRAM FOR
Q UNIT - 1,2,3 FAN**

SIZE A	DWG. NO. ES-Q WITH REVERSE OPTION
SCALE	DRAWN:
	DATE: 3/7/2024

REV.	DESCRIPTION	DATE	BY
	REVISIONS		

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE
PROPERTY OF LRC COIL CO. ANY REPRODUCTION IN PART OR WHOLE
WITHOUT THE WRITTEN PERMISSION OF LRC COIL CO. IS PROHIBITED