


HS120
VAH120

FACTORY & FIELD WIRING



1. USE COPPER CONDUCTORS ONLY
2. UNIT MUST BE GROUNDED
3. FOR MOTOR AMPS SEE RATING STICKER ON OUTSIDE OF UNIT.

SC= SPEED CONTROL
FACTORY WIRING —
FIELD WIRING - - - -

UNLESS OTHERWISE SPECIFIED
DIMENSIONS ARE IN INCHES
TOLERANCES ARE:
FRACTIONS DECIMALS ANGLES
+ .XX+ .XX + 1
.XXX+.XXX

CAD GENERATED DRAWING,
DO NOT MANUALLY UPDATE

APPROVALS		DATE
DRAWN	GA	12/10/2013
CHECKED		
RESP ENG		
MFG ENG		
QUAL ENG		

LRC COIL CO.
WIRING DIAGRAM
FOR : HS120, VAH120

A	INT. REL.	1/22/19	SV
REV.	DESCRIPTION	DATE	BY
REVISIONS			

NEXT ASSY	USED ON
APPLICATION	

DO NOT SCALE DRAWING

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF
VINOTEMP. ANY REPRODUCTION IN PART OR WHOLE WITHOUT
THE WRITTEN PERMISSION OF LRC COIL CO. IS PROHIBITED.

SIZE	DWG. NO.	REV.
A	ES-26702-00	A
SCALE	CAD FILE:	SHEET OF